



Figure 3 - 191. Staircase to Warden's Office (MBD P1000426.JPG)



Figure 3 - 192. Handprint (MBD P1010134.JPG)



Figure 3 - 193. Bootprint (MBD P1010310.JPG)



Figure 3 - 194a. Inscription in Officers' Row Terrace - "Tippy 575 7/2/46," behind Officers' Row 9 foundation wall. (Photo Courtesy of Shelagh Fritz (Officers' Row graffiti 1.jpg))



Figure 3 - 194b. Inscription in Officers' Row Terrace - "May 1, 19XX," located within Officers' Quarters 8 Garden (Photos Courtesy of Shelagh Fritz (Officers' Row graffiti 2.jpg, Officers' Row graffiti 3.jpg))



Figure 3 - 194c. Inscription in Officers' Row Terrace - "EM," located within remnant coal bin/garden storage structure in Officers' Quarters 8 Garden. (Photos Courtesy of Shelagh Fritz (Officers' Row graffiti 4.jpg, Officers' Row graffiti 5.jpg))



Figure 3 - 195. Pipe Railing (SR34) north of Restroom on Main Road (MBD P1000430.JPG)



Figure 3 - 196. Chain Railing (SR32) on Main Road between Switchback Three and Lighthouse. Note the circular outline of the coal delivery opening from the previous Officers Quarters in the road paving. (MBD SR32.JPG)



Figure 3 - 197. Security Railing (SR24) along east side of Officers' Row near Officers' Quarters 9, extends along north edge of Officers' Row, see photograph below (MBD IMG_2843.JPG)



Figure 3 - 198. 9a Stairs with SR24 security railing at far north end of Officers' Row (MBD IMG_2846.JPG)



Figure 3 - 199. Staircase between Officers' Quarters 9 and 8a gardens in Officers' Row (MBD IMG_2834.JPG)



Figure 3 - 200. Staircase between 8a gardens and Officers' Quarters 8 in Officers' Row (MBD IMG_2858.JPG)



Figure 3 - 201. Staircase between 8a gardens and Officers' Quarters 8 in Officers' Row with pipe railing (SR11) and decorative concrete railing (SR24) (MBD IMG_2856.JPG)



Figure 3 - 202. Stairs in Garden Terrace 7a in Officers' Row with pipe railing (SR11) on left (MBD IMG_2873.JPG)




Figure 3 - 203. Staircase between Officers' Quarters 7 and Warden's House garden in Officers' Row with pipe railing (SR12) and decorative concrete railing (SR35) (MBD IMG_2879.JPG)



Figure 3 - 204. Upper West Road looking north from near Lighthouse. Cellhouse Slope Garden is on right and concrete seatwall with pipe railing (SR36) in left of photo. Masonry block wall is on right (see structures). (MBD DCS03071.JPG)



Figure 3 - 205. Staircase to Toolshed and Cobble Walls. (MBD DSC03257.JPG)




Figure 3 - 206. Concrete Curb, Upper West Road, Road to Parade Ground on right, Toolshed in center between the two roads and Main Prison on the left (MBD IMG_4115.JPG)



Figure 3 - 207. Staircase to West Lawn, south of Stockade/Recreation Yard and accessed from Upper West Road, Main Prison is in the background (MBD IMG_4121.JPG)



Figure 3 - 208. Stone Wall at base of West Road Terrace; Main Prison in the background(MBD IMG_4114.JPG)



Figure 3 - 209. Road to Parade Ground looking south, Toolshed, Toolshed Terraces, Observation Blind, View to San Francisco in distance (MBD DSC03266.JPG)



Figure 3 - 210. Road to Parade Ground looking south, Observation Blind on right, View to Bay Bridge in background (MBD DSC03277.JPG)



Figure 3 - 211. Remnants of Road Tower foundation behind metal pipe railing, prison era fence in background. (SR62) (MBD DSC02886.JPG)



Figure 3 - 212. Rubble Curb, Toolshed Terraces, Reconstructed Toolshed (MBD DSC03265.JPG)



Figure 3 - 213. Concrete/Rubble Wall on east side of Road to Parade Ground, observation blind in far right of photo (MBD DSC03273.JPG)



Figure 3 - 214. Chain link safety railing (SR64), pipe railing (SR63) on concrete wall in left of photo, and metal pipe railing (SR62) in center of photo (MBD UWR_RPG_SB.JPG)



Figure 3 - 215. Observation blind on west side of Road to Parade Ground (MBD DSC03278.JPG)




Figure 3 - 216. Lower West Road looking south from Road to Parade Ground, View to San Francisco (MBD IMG_4120.JPG)



Figure 3 - 217. “Warning Keep Off” sign on Masonry Retaining Wall below former site of Road Tower, viewed from Incinerator area (MBD DSC02853.JPG)



Figure 3 - 218. Recesses in Rock (remnant supports for Perimeter Sentry Walk), Lower West Road retaining wall, “Warning Keep Off” sign on concrete retaining wall below Road Tower site (MBD Catwalk.JPG)

Vegetation - Main Road

Several gardens are located along the road. Although they were abandoned for several decades, remnants of these gardens still exist. Specifically, garden areas exist at the entrance to the Guardhouse Complex, on the slopes between the road's levels, adjacent to the Electric Shop, near Switchback Three, on terraces located adjacent to former Officers' Row houses, within two of the three building foundations at Officers' Row, adjacent to the Warden's House, on the slope southeast of the Main Prison, at the West Lawn and West Lawn Perennial Borders, and near the road's switchback on the west side of the Island. All garden areas in the Main Road Character Area have been rehabilitated except the West Lawn-South, which will remain an area for waterbird habitat.

Table 17: Vegetation - Main Road - Figure 3-229

<i>Feature (Type)</i>	<i>Bldg #</i>	<i>Figure #</i>	<i>Description</i>	<i>Condition</i>
Sallyport Garden with SR6 and SR8	22	3-219	Exhibits a diversity of ornamental plants as it did historically.	Good
Electric Shop Bed	89	3-220	Exhibits a diversity of ornamental plants as it did historically.	Good
Officers' Row	The terrace walls, basement walls, paths, stairs, and railings have been cleared of ivy and weeds. Brick and concrete edging still lines the paths and planting beds and stepping stones are still in place. (Officers' Row Gardens Treatment Plan) (Figure 3-116). See Table 14 Buildings – Main Road for individual images			
Officers' Quarters 7	7	3-117	Building foundation nearest to Warden's House. Restroom has been constructed on a portion of the site. Light groundcover exists.	Fair
Garden Terrace - 7a	7a	3-118	Four foot tall block wall planting beds just north of Officers' Quarters 7. Common plants include: <i>Narcissus sp.</i> , <i>Rosa sp.</i> , boxwoods, <i>Spirea sp.</i> , <i>Fuchsia sp.</i> , and heliotrope. ¹²	Good

¹² Byers and Ashford 2006b: 31

Table 17: Vegetation - Main Road, continued - Figure 3-229

<i>Feature (Type)</i>	<i>Bldg #</i>	<i>Figure #</i>	<i>Description</i>	<i>Condition</i>
Officers' Row, continued				
Officers' Quarters 8	8	3-119	Remnant brick foundation abutting the Trough Wall and a remnant coal bin/ garden storage that a portion of the Trough Wall as been built on top of. Common plants include: bearded Iris, <i>Crocosmia sp.</i> , <i>Rosa sp.</i> , <i>Centranthus ruber</i> , and <i>Limonium perezii</i> . ¹³	Good
Garden Terrace - 8a	8a	3-120	Terraced garden area just north of Officers' Quarters 8 site. Common plants include: <i>Lathyrus latifolius</i> , <i>Cistus</i> 'Sunset', <i>Pelargonium sp.</i> ¹⁴	Good
Officers' Quarters 9	9	3-121	Consists of partial brick and stone foundation walls. A garden and reconstructed c2007 Hothouse currently occupy the site. Common plants include: <i>Limonium perezii</i> , <i>Gazania sp.</i> , and <i>Pelargonium sp.</i> ¹⁵	Good
Garden Terrace - 9a	9a	3-122	Consists of three terraced levels with rubble retaining walls. At northern most end of Officers' Row. Monterey Cypress, <i>Agapanthus orientalis</i> , <i>Vinca major</i> , and <i>Oxalis</i> exist on the site. ¹⁶	Poor
Trough Wall		3-226	Ivy Leaf Pelargoniums planted in Trough Wall from SB3 to Lighthouse on Main Road	Good
Cellhouse Slope	68	3-222	Vegetated Slope below Main Prison Plaza. Planted with <i>Diosanthemum floribundum</i> , <i>Pelargonium</i> 'Prince Bismarck' and <i>Rosa</i> 'Felicite et Perpetue'	Fair
West Lawn	68	3-223	North - semi-overgrown lawn west of Main Prison (includes <i>Chasmanthe floribunda</i>). Perennial Lawn borders have been rehabilitated. South- completely hidden by tall overgrowth (<i>Ficus carica</i> , and <i>Albizia</i>).	North: Fair South: Poor
West Road Terraces		3-224	Terraced garden located south of Recreation Yard/Stockade. Exhibits a diversity of ornamental plants as it did historically.	Fair

¹³ Byers and Ashford 2006b: 30¹⁴ Ibid.¹⁵ Byers and Ashford 2006b: 29¹⁶ Ibid.

Table 17: Vegetation - Main Road, continued - Figure 3-229

<i>Feature (Type)</i>	<i>Bldg #</i>	<i>Figure #</i>	<i>Description</i>	<i>Condition</i>
Toolshed Terraces		3-225	Terraced garden north of the Toolshed. Species include <i>Echium candicans</i> , <i>Chasmanthe</i> , <i>Pelargonium sp.</i> , Spuria iris, <i>Rosa 'Felicite et Perpetue'</i> .	Fair
Rose Garden		3-227	New planting beds and gravel paths. On site of former 1882 Hospital	Good
Water Tank Terrace		3-228	Vegetation on terrace south of Water Tower. Species include: <i>Cordyline australis</i> , <i>Aeonium sp.</i> , and <i>Chasmanthe floribunda</i>	Poor
Main Road East Slope		3-131 3-133 3-137	Vegetated slope north of Switchback 2. Species include: Monterey Cypress, <i>Eucalyptus</i> , and <i>Prunus sp.</i> , as well as <i>Albizia distachya</i> , <i>Hedera Helix</i> , and <i>Centrathus ruber</i>	Fair

**Figure 3 - 219.** Sallyport Garden (MBD DSC02483.JPG)



Figure 3 - 220. Electric Shop Bed, retaining wall, and trench along west side of Main Road (MBD DSC02509.JPG)



Figure 3 - 221. Officers' Row Garden Plantings (MBD IMG_2860.JPG)



Figure 3 - 222. Cellhouse Slope (MBD DSC03067.JPG)



Figure 3 - 223. West Lawn - North (MBD DSC00197.JPG)



Figure 3 - 224. West Road Terraces (MBD P1000645.JPG)



Figure 3 - 225. Toolshed Terraces (MBD DSC03264.JPG)



Figure 3 - 226. Trough Wall (MBD P1000424.JPG)



Figure 3 - 227. Rose Garden (MBD P1000783.JPG)



Figure 3 - 228. Water Tank Terrace (MBD P1030008.JPG)

Archeological - Main Road

The potential archeological features of the Main Road consist of: buried defensive scarp Walls, buried batteries, dumping areas on shoals, possible garden remnants, and building remnants.

Table 18: Archeological - Main Road - Figure 3-230

<i>Feature</i>	<i>ASMIS #</i>	<i>Barker Inv #</i>	<i>Description</i>	<i>Condition</i>
Buried Defensive Scarp Walls - East Side	GOGA 00065; GOGA 00214	10; 12	<ul style="list-style-type: none"> • From Guardhouse Complex to Stores/QM Warehouse • Buried in slope formation, dating to 1870s (Chappell 1993; Martini 2003; Barker 2009) 	Undetermined
Lower Prison Kitchen Dump	GOGA 00215	13	<ul style="list-style-type: none"> • On slope north of Post Exchange ruins (Kelly 1981:3-4, Category 3) • Kitchens were in vicinity of Post Exchange and to south before base of Post Exchange was built (Barker 2009) 	Undetermined
Isolated Obsidian Lanceolate Point on Main Road	GOGA 00195	14	<ul style="list-style-type: none"> • Discovered by Alcatraz Garden Volunteer – from area of potential original grade (Barker 2008) 	Undetermined
NCO Quarters (Buildings 12, 13, 14)	GOGA 00220	20	<ul style="list-style-type: none"> • Four structures in 1867 (1867 Map) • Three structures in a later period (ref map) • Front wall foundation ruin, demolished in the 1940s (martini 2009) 	Undetermined
Officers' Row Foundation/ Structural Ruins (Buildings 7, 8, 9)	GOGA 00093	15	<ul style="list-style-type: none"> • Potential buried perimeter walls/structural ruins (Kelly 1981:2-1, Category 3; Barker 2006) • 7 was burned in 1970s and then demolished 	Undetermined
Hospital Steward's Quarters (Building 37)	GOGA 00223	23	<ul style="list-style-type: none"> • Possible re-use and/or debris (Kelly 1981:2-8, Category 3). 	Undetermined
Library Brick Footing (Building 47, 10A)	GOGA 00224	24	<ul style="list-style-type: none"> • Discovery in mascerator excavations – (archeology recorded after construction (Barker 2009) 	Undetermined
Hospital (removed after 1920)	GOGA 00226	26	<ul style="list-style-type: none"> • Possible re-use and/or debris (Kelly 1981:2-8, Category 2; Barker 2009) 	Undetermined

Table 18: Archeological - Main Road, continued - Figure 3-210

<i>Feature</i>	<i>ASMIS #</i>	<i>Barker Inv #</i>	<i>Description</i>	<i>Condition</i>
Blacksmith Shop, Furnace (Building 24)	GOGA 00205	28	<ul style="list-style-type: none"> • Adjacent to scarp wall and Battery Halleck (Battery 1) intersect 	Undetermined
Barker Beach and Slope Dump	GOGA 00272	78	<ul style="list-style-type: none"> • Entire Shoal around Island identified as area of potential submerged archeological potential (Kelly 1981: 3-15, Category 3 Barker, 2009) 	Undetermined
Battery Tower (Battery VIII)	GOGA 00273	79	<ul style="list-style-type: none"> • On Lower West Road at fork in the road (1867 map; Thompson 1979; Barker 2009) 	Undetermined
Magazine at Battery Tower	GOGA 00281	87	<ul style="list-style-type: none"> • (1867 Map; Thompson 1979: Map 1; Barker 2009:87) 	Undetermined
Furnace between Battery Tower and Battery McPherson	GOGA 00274	80	<ul style="list-style-type: none"> • On slope above Road to Parade Ground; west of pre-1940 (verify) playground (1867 map; Thompson 1979; Barker 2009) 	Undetermined
Battery McPherson (Battery IX)	GOGA 00275	81	<ul style="list-style-type: none"> • Possible buried remnants of pre-1894 battery • Under pre-1940 playground (verify) • (1875 map; Thompson 1979: Map 9, Kelly 1981:2-2, 3-10, Category 2 or 3, Barker 2009) 	Undetermined
Stable and Carriage House	GOGA 00284	90	<ul style="list-style-type: none"> • Behind western Battery McClellan • Stable was on east portion of west lawn and carriage house was on west portion of west lawn • (1867 map; Thompson 1979: Map 9; Barker 2009: 90) 	Undetermined